



ONLINE SERVICE HISTORY

Customer Copy





VEHICLE DETAILS

VIN: SALGA2BY7KA555477
MODEL: Range Rover / L405
ENGINE: 2L AJ20 P4H PHEV
COLOUR: SVO PREMIUM PALETTE BLACK
WARRANTY START DATE: 10/05/2019

REGISTRATION COUNTRY:
Not present

Please note that service intervals always represent the maximum time and distance that should exist between servicing. Driving style and conditions may necessitate earlier servicing as indicated by the notifications on your instrument panel.

SERVICE HISTORY

REPAIRER	JOB NUMBER	JOB DATE	ODOMETER	DETAILS
Brückner & Hofmann GmbH Wachtelberg 33 Kürnach Germany 97273 Germany	50726 	11/05/2023	93,082 km	Scheduled Service Completed 104,000 km/ 48 months service Related Service Items Renewal of Oil and Oil Filter Electronic Vehicle Health Check (eVHC) Renewal of Pollen Filter Renewal of Engine Air Filter Renewal of Spark Plugs Renewal of Alarm Handset Batteries Renewal of Ancillary Drive Belt Renewal of Rear Differential Fluid
Brückner & Hofmann GmbH Wachtelberg 33 Kürnach Germany 97273 Germany	47458 	13/05/2022	66,160 km	Scheduled Service Completed 78,000 km/ 36 months service Related Service Items Renewal of Oil and Oil Filter Electronic Vehicle Health Check (eVHC) Renewal of Brake Fluid Renewal of Transmission Fluid
Brückner & Hofmann GmbH Wachtelberg 33 Kürnach Germany 97273 Germany	43884 	15/06/2021	45,357 km	Scheduled Service Completed 52,000 km/ 24 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter
Brückner & Hofmann GmbH Wachtelberg 33 Kürnach Germany 97273 Germany	40088 	24/06/2020	21,300 km	Scheduled Service Completed 26,000 km/ 12 months service Related Service Items Renewal of Oil and Oil Filter Renewal of Pollen Filter



ONLINE SERVICE HISTORY

Customer Copy

VEHICLE DETAILS

VIN: SALGA2BY7KA555477
MODEL: Range Rover / L405
ENGINE: 2L AJ20 P4H PHEV
COLOUR: SVO PREMIUM PALETTE BLACK
WARRANTY START DATE: 10/05/2019

REGISTRATION COUNTRY:

Not present

Please note that service intervals always represent the maximum time and distance that should exist between servicing. Driving style and conditions may necessitate earlier servicing as indicated by the notifications on your instrument panel.

SERVICE HISTORY

REPAIRER	JOB NUMBER	JOB DATE	ODOMETER	DETAILS
Brückner & Hofmann GmbH Wachtelberg 33 Kürnach Germany 97273 Germany	35328 	09/05/2019	16 km	Scheduled Service Completed Pre-Delivery Inspection Related Service Items Not Applicable